


BK 31 Pg 13

CORNER RECORD

APN No. 057 - 2051 - 034 - 00 (Optional) Document Number CR 3476
 City of BERKELEY County of ALAMEDA, California
 Brief Legal Description MONUMENT REFERENCE AT THE INTERSECTION OF BERKELEY WAY
AND MILVIA STREET



CORNER TYPE

Government Corner ☐ Control ☒
 Meander ☐ Property ☐
 Rancho ☐ Other ☐
 Date of Survey SEPTEMBER 11, 2008

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner - Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐

In compliance with Section 8771 of the Professional Land Surveyors' Act, this corner record is being filed to
 ESTABLISH X / REESTABLISH _____ the position of an existing monument PRIOR X / SUBSEQUENT _____
 to street or highway reconstruction. (Use this portion only when applicable.)

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
REFERENCED EXISTING CITY OF BERKELEY MONUMENT B3022

A description of the physical condition of the monument as found and as set or reset: _____

SET CUT CROSS ON SIDEWALK

SET CUT CROSS ON TOP OF CURB

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyors' Act on Sept. 25 2008.

Signed Billy Martin L.S. or R.C.E. Number 5797




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 9-16 2008 and examined

and filed 11-9- 2008

Signed Russell R. Penland, Jr. Title: County Surveyor



County Surveyor's Comment _____

1"=40'

CITY OF BERKELEY MONUMENT B3022
FOUND 2" BRASS DISK WITH PUNCH
IN MONUMENT WELL

MILVIA STREET

BERKELEY WAY

- SET CUT CROSS ON CONCRETE PAD OF APARTMENT COMPLEX - ○
- SET CUT CROSS ON TOP OF CURB - □
- SET CUT CROSS ON BACK OF WALK - △
- FOUND CITY OF BERKELEY MONUMENT - ●