


CORNER RECORDDocument Number CR 7742City of BERKELEYCounty of ALAMEDA, CaliforniaBrief Legal Description CITY OF BERKELEY MONUMENT B0835**CORNER TYPE**

Government Corner ☐ Control ☒
 Meander ☐ Property ☐
 Rancho ☐ Other ☐
 Date of Survey OCTOBER 28, 2015

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 ☐ NAD83 ☐
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 ☐ NAVD88 ☐
 Meas. Units: Metric ☐ Imperial ☐

Corner – Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
IN COMPLIANCE WITH SECTION 8771 OF THE PROFESSIONAL LAND SURVEYORS' ACT, THIS CORNER
RECORD IS BEING FILED TO ESTABLISH THE POSITION OF AN EXISTING MONUMENT PRIOR TO
SANITARY SEWER RECONSTRUCTION. (SEE PAGE 2)

A description of the physical condition of the monument as found and as set or reset: _____
(SEE PAGE 2)

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Land Surveyor's Act on OCTOBER 30, 2015

Signed [Signature] P.L.S or R.C.E. No. 5003

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 11-25-2015

and examined and filed 12-14-2015

Signed Albert Jordan P.L.S or R.C.E. No. 4623

Title Deputy County Surveyor

County Surveyor's Comment _____

