


CORNER RECORDDocument Number CR 7337City of OAKLANDCounty of ALAMEDA, CaliforniaBrief Legal Description WELL MONUMENT LOCATED WITHIN GRAND AVE.**CORNER RECORD**

Government Corner ☐ Control ☒
 Meander ☐ Property ☐
 Rancho ☐ Other ☐
 Date of Survey 6/5/15

COORDINATES
(Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
FOUND BRASS DISK IN WELL MONUMENT IN FRONT OF 3606 GRAND AVE.

AS SHOWN ON CITY OF OAKLAND MONUMENT MAP, PAGE 240.

CITY MONUMENT DESIGNATION NUMBER AT SUBJECT LOCATION (LINDA ^{RM3}₉ BM)

THIS POINT WAS FOUND IN GOOD CONDITION AFTER A CONSTRUCTION PROJECT IN THE VICINITY.

A description of the physical condition of the monument as found and as set or reset: _____

FOUND POINTS AS SHOWN ON PAGE 2.


THESE TIES ARE FOR THE PURPOSE OF PERPETUATING THE FOUND MONUMENTATION.

NO CLAIM IS MADE AS TO THE RELATIONSHIP OF THE POINTS OR LINES SHOWN HEREON
 TO TRUE BOUNDARY LOCATIONS.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Land Surveyors' Act on JUNE 9, 2015.

Signed Vincent H. Cunha L.S. Number LS 4520
 VINCENT H. CUNHA

**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received 6-11-2015 and examined

and filed 7-10-2015

Signed Russell R. Penland Title County Surveyor



County Surveyor's Comment SEE PRE-CONSTRUCTION CR 6380



SCALE: 1"=30'

LEGEND

- ⊙ FOUND BRASS DISK IN MONUMENT WELL (LINDA RM3 BM)
9
- ✕ FOUND CUT CROSS IN CONCRETE
- AA###A# ALAMEDA COUNTY MONUMENT ID

NOTE

ELEVATIONS SHOWN HEREON ARE BASED UPON
CITY OF OAKLAND VERTICAL DATUM
LINDA RM NO. 3 TAKEN AS ELEV.=13' TO THE
NEAREST FOOT.

